



PERFORMANCE BULLETIN

 Product Application Service General

news from


**Pentair**
Water Treatment

August 26, 2000

Mallory® Timer Motor Caution

It has come to our attention that the gear train in the drive motors used on residential control valves and timers may be damaged by rough handling. Dropping the motor, or handling in a manner that the gear and output pinion shaft are subject to an impact load, may cause failure of the gear train. Please use caution when handling these and all motors.

The gear is connected to
the output pinion shaft.



The New Upflow Service Manuals

We are changing the upflow service manual appearance. In the past, the upflow service manuals had green print and pictures with white pages. The new change of the upflow service manuals will have black print with green pages. As the service manuals are reprinted, you will see the new change. This will help to identify the difference between upflow and downflow service manuals.

As always, thank you for using Fleck controls.

Sincerely,
Pentair Water Treatment, Inc.

Jay Runkle
Technical Product Support