



# PERFORMANCE BULLETIN

Product     Application     Service     General    news from



September 12, 2003

## Temporary Production Hold

Due to performance issues, the 4650 hot water option has been placed on hold until further analysis can be completed. Currently in some applications, the second piston seal may tear when exposed to consistent high temperature ranges (>140F). This failure results in a leak to drain during service.

Please contact your Customer Service Representative or Sales Manager to obtain pricing and specifications for alternative hot water control valves for applications greater than 140F until a permanent solution can be implemented.

We apologize for the inconvenience and thank you for your patience as we work to resolve the issue.

As always, thank you for using Fleck controls.

Sincerely,  
Pentair Water Treatment

Wayne Ploense  
Technical/Sales Support