

Performance Bulletin

Product Application Service General


June 2005

New Integral Motor Bracket Available

Starting September 2005, a new integral motor bracket is available for the 1500, 2510, 2750, 2850, and the upper drive motor on the 2900s. The motor is retro-fittable with existing backplates and will replace the existing motors and brackets for these models.

Features and Benefits:

- Easy to remove and install
- Integral brackets provide improved support
- Less components to keep in inventory
- Integral brackets insure proper switch location
- Greater corrosion resistance, giving longer life in humid environments
- Ground location reduced from two to one



Please see the following page for a chart showing part number replacements.

As always, thank you for using Fleck Controls.

Sincerely,
Pentair Water, Inc.
Elizabeth Beasley

Elizabeth Beasley
Technical Communications

Previous Part Number	Description	Replacement Part Number
40385	24V/50-60 Hz Drive Motor	41544
11826	Brine Bracket	
10774	Motor Bracket	
10872	Screw	

Previous Part Number	Description	Replacement Part Number
40384	115V/50-60 Hz Drive Motor	41543
11826	Brine Bracket	
10774	Motor Bracket	
10872	Screw	

Previous Part Number	Description	Replacement Part Number
40386	230V/50-60 Hz Drive Motor	41545
11826	Brine Bracket	
10774	Motor Bracket	
10872	Screw	