

A FLECK PERFORMANCE BULLETIN

Product Application Service General **news from Fleck Controls**

January 19, 1998

2900 Lower Drive Cam Breaking

We have heard reports of some lower drive cams breaking on 2900 valves. Testing has confirmed a problem we had in-house with the cams. New cams have been received and tested on Monday, January 15, 1998. This batch passed our testing and production has resumed with all in-house inventory being rebuilt. The questionable drive cams were used on 2900 valves, serial numbers 4203920 through 4295081, manufactured between October 2, 1997 and January 14, 1998.

If you have a 2900 valve and are experiencing this problem, please contact customer service to obtain replacement parts. The cam assembly is P/N 14775 and roll pin is P/N 11381.

As always, thank you for using Fleck Controls.

Sincerely,

Fleck Controls, Inc.
Technical Product Support