

A FLECK PERFORMANCE BULLETIN

Product Application Service General **news from Fleck Controls**


July 14, 1998

Plastic Bypass

When we first introduced the plastic bypass we did not identify the inlet and outlet port.

We have recently added a white marking to the top of the bypass plugs on the inlet and outlet sides of the bypass to help identify the bypass plugs in a low light area.

During the transition period, you may have seen some by-passes with a white mark on the outlet side only.



As always, thank you for using Fleck Controls.

Sincerely,

Fleck Controls, Inc.
Technical Product Support