

A FLECK PERFORMANCE BULLETIN

Product Application Service General **news from Fleck Controls**

May 28, 1999

2900 Lower Drive Cam Improvement

This new cam is stronger and has a molded hole for the connecting rod bearing. Having the molded hole, always in a fixed position, allows for a consistent alignment of the micro switches on the cam and increased product reliability. This change was implemented on May 1, 1999.

Part numbers:	14775	Cam
	60160-21	Cam assembly for Standard Backplate
	60160-22	Cam assembly for Environmental Backplate


SIDE VIEW



Old Style

New Style

TOP VIEW



As always, thank you for using Fleck Controls.

Sincerely,
Pentair Water Treatment, Inc.

Jay Runkle
Technical/Product Support