

A FLECK PERFORMANCE BULLETIN

Bulletin No. 342

Product Application Service General **news from Fleck Controls**

July 28, 1999

SE Timer Program Caution

The currently available SE timer should not be programmed as follows:

* Regeneration Type

Metered Immediate
7 - - 2



* Regeneration Day Override

Regenerate everyday
A - - 1



This will allow the timer to lock itself and continuously regenerate. If this happens, the timer must be replaced. The upgrade version of this timer will not have this problem and is expected to be available in August of '99 for the 5000SE and TwinFlow100e control valves. The 5600SE is expected to be available in October '99.

As always, thank you for using Fleck Controls.

Sincerely,
Fleck Controls, Inc.



Jay Runkle
Technical/Product Support