



PERFORMANCE BULLETIN

 Product Application Service General

news from



January 20, 2000

White Rapid Rinse Cam to be Discontinued

Effective February 1, 2000, the white rapid rinse cam, part # 12102, (drive cam), and part # 10815, (brine side cam), will be discontinued.

White cams are currently available as an option on the 1500, 2500, 2510, 2700, 2750, and 2850 valves. The cams that will replace the white rapid rinse cams, are the black separate time fill cams, part # 12576, (drive cam), and part # 12777, (brine side cam). Future ordering guide updates will reflect these changes. NOTE: When converting from a white cam to a black cam, it is necessary to add 2 pins to the timer program wheel to shut off brine tank refill.

There are some definite advantages to the black cam. It is capable of operating an auxiliary switch, whereas the white cam cannot. It is also easier to convert from a softener to a filter, and from a filter to a softener, when using a black cam.

As always, thank you for using Fleck controls.

Sincerely,
Pentair Water Treatment, Inc.

Jay Runkle
Technical Product Support