



PERFORMANCE BULLETIN

Product Application Service General news from



November 14, 2003

New 4650 Hot Water Seal

In order to ensure a longer service life for the 4650 valve in water temperatures up to 180⁰ Fahrenheit, we have replaced the standard ethylene propylene seals with a more durable silicone seal. The silicone seals are blue in color and available for sale as service replacement parts or configured in standard product.



Fleck recommends that all hot water pistons, seals, spacers, and brine valves undergo maintenance as part of a yearly service schedule.

The 4650 hot water service part numbers are as follows:

17772 SEAL, 4650 HOT WATER

60125-10 SEAL&SPACER KIT, 4650 HOT WATER

As always, thank you for using Fleck controls.

Sincerely,

Pentair Water Treatment, Inc.

Wayne Ploense
Technical Sales/Support