

# Performance Bulletin

---

Product     Application     Service     General

May 27<sup>th</sup>, 2005

## Improved Plastic Bypass

Improvements have been made to the 60049 plastic bypass valve, and will be integrated as a running change beginning June of 2005.

### Features and Benefits:

- **Handle Improvement:**
  - Arrows (designed on handles) indicate water flow in service
  - Accommodates a drain line straight out the back when in service or stand-by
  - Easier to operate when o-rings have become seated over time
  - Improved aesthetic design
- Accommodates the drain port on the 5600 Valves (1/2" straight hose barb (part number 13308) and 90 degree elbow (part number 12338))




Please see the following page for water flow path positions.

As always, thank you for using Fleck Controls.

Sincerely,  
Pentair Water, Inc.  
*Elizabeth Beasley*

Elizabeth Beasley  
Technical Communications

# Water Flow Path Positions



## 3. Checking Backflow (Cross Connection Check)

