

Performance Bulletin

Product Application Service General

July 2005

60049 Plastic Bypass Updates & Availability

Material Change:

The material for the bypass is now the same fiber reinforced polymer that is used on our standard valve bodies. This affects all of the components in the assembly, increasing the bypass's chemical resistance.

"Checking Backflow" Flow Path Change:

The third flow path in Performance Bulletin #435 has changed. Please see the following page for all flow paths.

Beginning in July, the new and improved 60049 plastic bypass will become available for orders.




41687 Wrench for Re-Designed Plastic Bypass

Beginning in July, a wrench is available (part number 41687) for the new plastic bypass (part number 60049).


Please see Performance Bulletin #435 for additional information.

As always, thank you for using Fleck Controls.

Sincerely,
Pentair Water, Inc.




Elizabeth Beasley
Technical Communications




Water Flow Path Positions

1. Bypass



2. Service



3. Checking Backflow (Cross Connection Check)

Revised Flowpath

