

Performance Bulletin

July, 2006

2850 Piston Rod Color Change


The color on the 2850 piston Rod (p/n 16436, and by-pass piston assembly p/n 60105) is changing from grey to black. The reason for the change is for easier part differentiation, and it will be changed as inventories are depleted.



Old Color (Grey) on Left and New Color (Black) on Right

As always, thank you for using Fleck Controls.

Sincerely,
Pentair Water, Inc.



Elizabeth Beasley
Technical Communications