


Performance Bulletin

December 2006

Piston Rod Color Change from Black to Gray


Beginning in December of 2006, the color on the 2850 piston rod (part number 16436) will change from black to gray. The reason for this change is due to the black coating no longer being produced by our vendor. Please see the photo below for a comparison of the old color to the new.



**Top Piston Rod (with Black Color) and
and Bottom Piston Rod (with Gray Color)**

As always, thank you
for using Fleck Controls.

Sincerely,
Pentair Water, Inc.



Elizabeth Beasley
Technical Communications