

Performance Bulletin

May 2007

Blue Cam Replacing Black Cam on 1500, 2510, 2750, & 2850 Valves

Beginning on May 23rd, 2007, all black cams on the 1500, 2510, 2750, and 2850 valves will be replaced with blue cams. This change has already happened on the 2900 valve.

The blue color allows for easier identification, and enhancements have been made for more accurate piston positioning.

The black cam's assembly number is 60160-10 (Drive Cam Assy, STF, Black) and the blue cam assembly number is 60160-15 (Drive Cam Assy, STF, Blue). The blue cam is retrofitable.

