


Performance Bulletin

October 2007


Motor Drive Assembly Changes

Effective immediately as a running change as inventory depletes, there will be changes to the look of three motor drive assemblies. The switch insulators and the spacer washers on the auxiliary switch will be removed. The gear case has higher bosses for mounting the switches to accomplish this change. The motor gear case with this change has an identification boss on top. Existing product in the field should be used with the insulators and spacer washers to achieve good alignment of the switch on the cam. If a new motor in the field is accidentally used with insulators and spacer washers, the switches will still function. The assembly numbers will remain the same.

Motor Drive Assemblies	
Part No.	Description
41543	Motor, Drive, 115V, 50/60 Hz
41544	Motor, Drive, 24V, 50/60 Hz
41545	Motor Drive, 230V, 50/60 Hz



Old Motor with Microswitch Insulators & Spacer Washers
(see red arrows)



New Motor without Microswitch Insulators & Spacer Washers
(red arrow shows new identifying mark)