



PERFORMANCE BULLETIN

 Product Application Service General

news from

**Pentair**
Water Treatment

September 14, 2000

Caution Installing the 9 Volt Battery On A 6600/6700 Timer

Before installing or replacing a 9-volt battery in a 6600 or 6700 control valve, it is recommended that the valve be first operated from line power. Failure to do this could lead to a malfunction of the timer. This applies to 6600 and 6700 control valves manufactured between May 22, 2000 and August 28, 2000 (serial numbers 5273294 - 5397922). This malfunction will cause a blank display and an inoperable valve.

Malfunction Recovery:

1. Unplug the 9V battery from the timer and the valve from line power for about one minute to clear the malfunction.
2. Plug the valve into line power.
3. Plug the 9V battery into the timer's battery harness.

As always, thank you for using Fleck controls.

Sincerely,
Pentair Water Treatment, Inc.

Jay Runkle
Technical/Product Support