



PERFORMANCE BULLETIN


Product Application Service General news from



April 14, 2004


The 7000 Yoke Connectors

1" Inside or 1 1/4" outside (Brass)



41242-01 Brass Connector, 1" & 1 1/4"-
Sweat (W/O-ring)

1 1/4" Inside or 1 1/2" outside (Brass)



41243-01 Brass Connector, 1 1/4" & 1 1/2"-
Sweat (W/O-ring)

1" NPT or BSP (Plastic)



40563-01 Plastic 1" Connector NPT (W/O-ring)
40563-11 Plastic 1" Connector BSP (W/O-ring)

1 1/4" NPT or BSP (Plastic)



40565-01 Plastic 1-1/4" Connector NPT (W/O-ring)
40565-11 Plastic 1-1/4" Connector BSP (W/O-ring)

⚠ CAUTION – When sweating the Brass connectors be sure to remove o-ring and disconnect from valve before heating.

⚠ CAUTION – When using the Plastic connectors be sure to use Teflon tape on threads we recommend not using pipe dope.

As always, thank you for using Fleck controls.

Sincerely,
Pentair Water Treatment, Inc.

Ken Mills

Ken Mills
Technical Sales/Support