


Performance Bulletin


January 2007

Meter Assembly Changes


Beginning in January of 2007, the plastic meter assemblies will be changing in appearance. The reason for this change is to improve the assembly process, eliminate the need to glue parts, and increase structural integrity. The new assemblies are pictured below. They carry the same part numbers, are interchangeable, and will function with the existing meter checkers. They will also be available on brass meter assemblies (cold water applications only). Please reference Performance Bulletin #524 (Brass Meters Available with Plastic Caps) for additional information.




15150 Meter Cap Assembly
60087 Meter Assembly




15659 Meter Cap Assembly
60089-180 Meter Assembly



15452 Meter Cap Assembly
60088-180 Meter Assembly
Not Shown: 60088-0



15452-01 Meter Cap Assembly
60088-45 Meter Assembly



14038 Meter Cap Assembly
60086 Meter Assembly

As always, thank you
for using Fleck Controls.

Sincerely,
Pentair Water, Inc.

Elizabeth M. Beasley
Elizabeth Beasley
Technical Communications