



# Performance Bulletin

---

March 2007

## **Cam Switch Changes on 9000/9100/9500 Valves**

Effective immediately, there will be a change on the cam switches for the 9000, 9100, and 9500 valves. Instead of part number 10218 (Switch, Micro) and 16433 (Switch, Miniature) both being on the valves, our customers will receive two of part number 16433. The reason for this change is to eliminate confusion between having two different switches on the valves.

Thank you for using Fleck Controls.

Sincerely,  
Pentair Water, Inc.

A handwritten signature in black ink that reads "Elizabeth M. Beasley".

Elizabeth Beasley  
Technical Communications