


Performance Bulletin


December 2007

New Circuit Board on 3200NT

Effective as a running change as inventory depletes, the 3200NT timers will begin the transition to a new circuit board. The new board does not affect any of the current functions. The most noticeable difference will be in the removal of the Mylar® cover on the back of the timer. Since the Mylar® cover will be removed, the new circuit board has the text imprinted on it. This change is being made due to vendor discontinuation of components on the older circuit boards.



New 3200NT Circuit Board
(Not Actual Size)



Old 3200NT Mylar Cover
(Not Actual Size)